

HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

Marvine Colliery, Breaker No. 2
West side of Boulevard Avenue, between
East Parker Street and Interstate Route 380
Scranton
Lackawanna County
Pennsylvania

HAER No. PA-183-C

HAER
PA
35-SCRAN
6C-

NOTE: Photographs were taken by Dorothy Silva, architectural historian, April 1990

- PA-183-C-1 VIEW OF EAST FRONT OF BREAKER, WITH SCALE STICK, SHOWING FOUNDATIONS OF RETAIL SCALES IN FOREGROUND, LOOKING WEST
- PA-183-C-2 VIEW OF EAST AND NORTH FACADES OF BREAKER, WITH BOILER HOUSE AT LEFT, LOOKING SOUTHWEST
- PA-183-C-3 VIEW OF SOUTH FACADE OF BREAKER, LOOKING NORTH
- PA-183-C-4 VIEW OF WEST AND SOUTH FACADES OF BREAKER, WITH CHANCE CONE AT WEST, LOOKING NORTHEAST
- PA-183-C-5 DETAIL VIEW OF CHANCE CONE, LOOKING NORTH-NORTHWEST
- PA-183-C-6 INTERIOR VIEW OF BREAKER, FIRST FLOOR, DEPICTING PIPING AND CHUTES IN FORMER CHANCE CONE AREA, LOOKING NORTH-NORTHWEST
- PA-183-C-7 INTERIOR VIEW OF BREAKER, FIRST FLOOR, LOOKING EAST-NORTHEAST
- PA-183-C-8 DETAIL VIEW OF INTERIOR OF BREAKER, FIRST FLOOR, SHOWING COAL CHUTES AND WATER PIPING, LOOKING SOUTHWEST
- PA-183-C-9 DETAIL VIEW OF INTERIOR OF BREAKER, FIRST FLOOR, DEPICTING CHUTES AND ELECTRIC MOTOR, LOOKING EAST-SOUTHEAST FROM ELEVATED PLATFORM AT NORTH END
- PA-183-C-10 DETAIL VIEW OF INTERIOR OF BREAKER, SECOND FLOOR, SHOWING PUMP HOUSING FROM RUIN OF WALL AT EXTERIOR NORTH FACADE, LOOKING SOUTHEAST


Marvine Colliery, Breaker No. 2
HAER No. PA-183-C
Index to Photographs
(Page 2)

- PA-183-C-11 Photocopy of photograph. Photographer unknown, circa 1955.
Original photograph can be found in "Marvine Colliery" folder in the archives of the Lackawanna Historical Society, Scranton, Pennsylvania.
VIEW SHOWING EAST AND NORTH FACADES OF BREAKER, WITH BOILER HOUSE AT FAR LEFT AND RETAIL SCALES OFFICE DIRECTLY EAST OF BREAKER, LOOKING SOUTHWEST
- PA-183-C-12 Photocopy of photograph. Horgan, circa 1922
Original photograph can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
VIEW DEPICTING PORTION OF BREAKER NO. 2 NORTH FACADE AT FAR LEFT, WITH CONVEYOR LINE TO BREAKER NO. 1 AT FAR RIGHT, LOOKING SOUTH
- PA-183-C-13 Photocopy of photograph. Photographer unknown, circa 1940.
Original photograph can be found in "Marvine Colliery" folder in the archives of the Lackawanna Historical Society, Scranton, Pennsylvania.
VIEW SHOWING SOUTH AND EAST FACADES OF BREAKER, WITH OVERHEAD PIPING IN FOREGROUND AND RETAIL SCALES OFFICE AT FAR RIGHT, LOOKING NORTHWEST
- PA-183-C-14 Photocopy of photograph. Horgan, 1922. Negative #D & H 22413
Original negative can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
VIEW SHOWING EAST FACADE OF BREAKER, WITH RETAIL SCALES OFFICE IN FOREGROUND, LOOKING WEST
- PA-183-C-15 Photocopy of photograph. Horgan, 1920.
Original negative can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
VIEW SHOWING BREAKER UNDER CONSTRUCTION, LOOKING EAST
- PA-183-C-16 Photocopy of photograph. Horgan, December 6, 1920
Original negative can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
VIEW SHOWING BREAKER UNDER CONSTRUCTION, LOOKING WEST
- PA-183-C-17 Photocopy of photograph. Horgan, September 7, 1920. Negative #D & H 20907
Original negative can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
DETAIL VIEW SHOWING CONSTRUCTION OF CONVEYOR TUNNEL, LOOKING SOUTHWEST

Marvine Colliery, Breaker No. 2
HAER No. PA-183-C
Index to Photographs
(Page 3)

- PA-183-C-18 Photocopy of photograph. Horgan, date unknown.
Original negative can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
DETAIL VIEW OF SLUSH TROUGH FROM BREAKER NO. 2 TO BOREHOLE UNDER NORTH END OF BOILER HOUSE NO. 2, LOOKING SOUTH
- PA-183-C-19 Photocopy of photograph. Horgan, 1922.
Original photograph can be found in "Marvine Colliery" folder in the archives of the Lackawanna Historical Society, Scranton, Pennsylvania.
INTERIOR VIEW OF BREAKER, SHOWING SIZED AND WASHED COAL IN COAL CARS, WITH MINING INSPECTORS
- PA-183-C-20 Photocopy of photograph. Horgan, February 7, 1921. Negative #D & H 21895
Original negative can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
INTERIOR VIEW OF BREAKER, TOP FLOORS, SHOWING DETAIL OF TOP SCREENS AND CRUSHERS AT TIME OF CONSTRUCTION
- PA-183-C-21 Photocopy of photograph. Horgan, December 28, 1920. Negative #D & H 21849
Original negative can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
INTERIOR VIEW OF BREAKER, MIDDLE FLOOR AREA, SHOWING DETAIL OF INSTALLATION OF FINE COAL SHAKERS AT TIME OF BREAKER CONSTRUCTION
- PA-183-C-22 Photocopy of photograph. Horgan, November 22, 1920. Negative #D & H 20969
Original negative can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
DETAILED INTERIOR VIEW SHOWING TOP OF JIGS AT TIME OF BREAKER CONSTRUCTION
- PA-183-C-23 Photocopy of photograph. Horgan, December 28, 1920. Negative #D & H 21850
Original negative can be found in "D & H" collection of the Anthracite Heritage Museum, Scranton, Pennsylvania.
DETAILED INTERIOR VIEW OF FIRST FLOOR LOADING CHUTES AT EAST END OF BREAKER
- PA-183-C-24 Photocopy of photograph of sketch. Artist and photographer unknown, circa 1930.
Original sketch can be found in "Marvine Colliery" folder in the archives of The Lackawanna Historical Society, Scranton, Pennsylvania.
ARTIST'S RENDERING OF CHANCE CONE, "HUDSON COAL COMPANY, SCRANTON, PA"

KEY TO PHOTOGRAPHS
 MARVINE COLLIERY: Breaker No. 2
 HAER No. PA-183-C (page 4)



FIRST FLOOR